1023 UNSAFE CONSTRUCTION WORK

Y C Lu* *Correspondence to Sophia Mineral Corp, Unit 1514 President Tower, 81 Tlmog Avenue, Quezon City 1100, Philippines*

10.1136/ip.2010.029215.1023

The construction industry in the Philippines has been reminding on its safety compliance. Many falls and deaths have been reported by media due to lack of safety belt, unsafe practices of using installed elevators that suddenly drop, stepping on unstable platforms, and sleepiness and nightshift overtime work.